

Z AXIS DIAL TOOL SETTING GAUGE - PMZB



Dimensions (mm)		
Part Number	Height	Weight (kg)
9002/50B	50 ± 0,005	1,2

Use : Setting tool length on CNC milling

Features :

- Height: 50 ± 0.005 mm
- Large measuring surface.
- Low spring force to avoid tool damaging.
- Easy calibration setting.

